



QUOTE

Merriott Parish Council

Date
20 May 2026

Expiry
19 Jun 2026

Quote Number
QU-0723

Reference
180526-02

VAT Number
478405268

Inspect and Repair
7 Cedar Close
Chard
Somerset
TA20 1DB

Description	Quantity	Unit Price	VAT	Amount GBP
Remove redundant cable ties (included in labour charge)	1.00	0.00		0.00
Replace worn wooden panels on benches	3.00	59.99	20%	179.97
Remove support struts and reweld on basketball hoop	1.00	200.00	20%	200.00
Sand and apply metal paint to slow rate of rust on lat pull	1.00	50.00	20%	50.00
Tighten fixings on arm pedal bike (Included in labour charge)	1.00	0.00		0.00
Tighten fixings at ground level on double air walker (Included in labour charge)	1.00	0.00		0.00
Replace 8 internal rubber stoppers on double air walker	1.00	249.00	20%	249.00
Replace plastic dome cover on triple pull up station	1.00	89.99	20%	89.99
Plastic End Cap for snake swing	8.00	2.50	20%	20.00
Temporarily remove trampoline bed, clear nettles and litter and reattach trampoline bed (Included in labour charge)	0.00	0.00		0.00
Replace rivet with flush nut and bolt and infill cavity with topsoil (4 bags)	1.00	80.00	20%	80.00
Plastic End Cap on rolling drum	2.00	2.50	20%	5.00
Sand and apply metal paint to slow rate of rust on small basket swing	1.00	50.00	20%	50.00
Plastic End Cap on rope slide	6.00	2.50	20%	15.00
Replace 3 worn steps on small metal climbing frame with slide	1.00	119.00	20%	119.00

Description	Quantity	Unit Price	VAT	Amount GBP
Wooden Post 150mm (Per Metre) on horizontal metal bars	2.00	99.00	20%	198.00
Wooden Post 150mm (Per Metre) on horizontal metal bars	2.00	99.00	20%	198.00
Wooden Post 150mm (Per Metre) on monkey bars	3.60	99.00	20%	356.40
Wooden Post 150mm (Per Metre) on monkey bars	1.50	99.00	20%	148.50
Various caps on fresh air fitness equipment	1.00	80.00	20%	80.00
Zip line chain guard	1.00	279.00	20%	279.00
Move Spring break further along cable to eliminate risk of user hitting wooden framework on zip line (Included in labour charge)	1.00	0.00		0.00
Tighten fixings on large basket swing (Included in labour charge)	1.00	0.00		0.00
Engineer Labour Charge to fit all above, 2 engineers including all consumables	1.00	680.00	20%	680.00
Subtotal				2,997.86
TOTAL VAT 20%				599.57
TOTAL GBP				3,597.43